



HARMONY 143.000
 PICTURE WINDOW
 NEW CONSTRUCTION WINDOW
 BRICKMOULD WITH WOOD JAMBS
 WELDED ASSEMBLY